



Festo AG & Co. KG

Postfach  
73726 Esslingen  
Germany  
+49 711 347-0  
www.festo.com

## Axial kit EAMM-A-E...-...A

### 1. Intended usage

Axial kit EAMM-A-E...-...A:  
Connecting an axis to a motor in axial configuration to the driven shaft  
(→ Section 9).

### 2. Safety instructions and notes on mounting

#### ⚠ Caution

Unexpected movement of components.

Injury due to impact or pinching.

- Switch off power supply before mounting work.
- Observe the safety instructions (→ applicable documents).

#### → Note

Incorrect mounting can cause malfunction and material damage.

- Observe tightening torques (→ Section 7).
- Leave lubricant film on the screws.
- Clean shafts. The coupling **1** will only grip without slipping on a drive shaft which is dry and free of grease.

- Observe proper alignment of coupling **1** (→ Section 6).

- Support the combination (→ Section 8):

- if there are far-protruding or heavy motor attachments
- if there are severe vibrations or oscillation/shock loads

Each time after disconnecting or turning the motor:

- Perform a homing of the axis.

#### i Info

#### Applicable documents

- Motor operating instructions
- Axis operating instructions


The kit contains all the mounting components that may be required.  
Select required mounting components (→ Section 7).

There are two mounting variants (A/B).


EAMM-A-...	Mounting variants
E20-...A	A
E32/E48/E72-...A	B

### 3. Parts lists

#### 3a. Mounting variant A parts list




#### 3b. Mounting variant B parts list




#### 4. Coupling preassembly

##### 4a. For mounting variant A (DMES-18)




- Remove axis adapter (B).




- Slide coupling **1** with the matching drill hole onto the drive shaft (A).
- Lightly screw on motor-side clamping screw **2**.

For accurate alignment:

- Observe distance (X) (→ Section 6).
- Tighten axis-side clamping screw **2**.



- Fasten the axis adapter (B) on the axis's actuator end cap using the screws (C).




For accurate alignment:

- Observe distance (Z) (→ Section 6).

- Align the angular position of the coupling **1**.  
Check: the motor-side clamping screw **2** will be accessible later through a drill hole in the coupling housing **4**.

##### 4b. For mounting variant A (DGE-18-SP)



- Slide coupling **1** with the matching drill hole onto the drive shaft (A).
- Lightly screw on motor-side clamping screw **2**.

For accurate alignment:

- Observe distance (Z) (→ Section 6).


- Tighten axis-side clamping screw **2**.

The axis-side clamping screw **2** is accessible through a drill hole in the actuator end cap.

- Align the angular position of the coupling **1**.

Check: the motor-side clamping screw **2** will be accessible later through a drill hole in the coupling housing **4**.

##### 4c. For mounting variant B



- Slide coupling **1** with the matching drill hole onto the drive shaft (A).
- Lightly screw on motor-side clamping screw **2**.

For accurate alignment:


- Observe distances (X and Y) (→ Section 6).
- Tighten axis-side clamping screw **2**.

- Align the angular position of the coupling **1**.


Check: the motor-side clamping screw **2** will be accessible later through a drill hole in the coupling housing **4**.

### 5. Mounting


#### 5a. For mounting variant A




- Fasten coupling housing **4** to the axis using the screws **6**.




- Fasten motor flange **8** to the coupling housing **4** using the screws **9**.



- Connect motor to axis by pushing.  
Check: the motor's drive shaft has been inserted into the coupling **1**.
- Fasten motor to the motor flange **8** using the screws **11**<sup>1)</sup>.



- Tighten motor-side clamping screw **2** through a drill hole in the coupling housing **4**.




- Push cover caps **14** into the drill holes in the coupling housing **4**.

Continuation on the reverse side!

<sup>1)</sup> For the ...-42A kit, the motor flange **8** is fastened to the motor using the screws **11**.

### 5b. For Mounting variant B



- Fasten coupling housing [4] to the axis using the screws [6].
- Fasten motor flange [8] to the coupling housing [4] using the screws [9].
- Connect motor to axis by pushing. Check: the motor's drive shaft has been inserted into the coupling [1].
- Fasten motor to motor flange [8] using the screws [11].
- Tighten motor-side clamping screw [2] through a drill hole in the coupling housing [4].
- Push cover caps [14] into the drill holes in the coupling housing [4].


### 6. Coupling [1] alignment

#### → Note


Axial forces on the shafts of motor and axis can result in failure of the encoder/brake or increased bearings wear.

- Observe distances X, Y and Z.

For mounting variant A:



For mounting variant B:



EAMM-A-	X ±0.5 [mm]	Y ±0.5 [mm]	Z ±0.5 [mm]
E20-40A	30	-	16
E20-42A			
E20-55A			
E32-40A	18.5	35	-
E32-55A			
E32-57A			
E32-67A	36	66	-
E48-55A <sup>2)</sup>			
E48-57A <sup>2)</sup>			
E48-44A-70A <sup>2)</sup>			
E48-64A-70A <sup>3)</sup>			
E48-67A			
E48-87A			
E48-100A	47.5	66	-
E72-70A			
E72-87A			
E72-100A			

### 7. Screw sizes and tightening torques<sup>4)</sup>


EAMM-A-	[2]	[Nm]	[6]	[Nm]	[9]	[Nm]	[11]	[Nm]								
E20-40A	M3x4	1.5	M4x22	3	M3x10	1.2	M3x14	1.2								
E20-42A					M3x20		M3x10									
E20-55A					M3x16		M5x18		6							
E32-40A	M4x12	3	M4x35	3	M4x12	3	M3x16	1.2								
E32-55A					2.4		M5x18		6							
E32-57A					3		M4x12		3							
E32-67A	M4x12	3	M5x50	6	M4x12	2.4	M5x18	6								
E48-55A					3		M4x12		3							
E48-57A					2.4		M5x18		6							
E48-44A-70A					M6x16		10.5		M5x70	M6x12	8	M5x20	8			
E48-64A-70A												M6x16		10	M6x16	8
E48-67A												M6x22		10		
E48-87A	M6x20	10.5	M8x90	18	M6x12	8	M5x20	6								
E48-100A							M6x16		10	M6x22	10					
E72-70A							M6x20		18	M8x25	18					
E72-87A	M6x16	10.5	M8x90	18	M6x12	8	M5x20	6								
E72-100A							M6x22		10	M8x25	18					

<sup>2)</sup> DMES-40 is not permissible for EAMM-A-E48-55A, E48-57A and E48-44A-70A.

<sup>3)</sup> DGE-SP-40 is not permissible for EAMM-A-E48-64A-70A.

<sup>4)</sup> Tolerance for M<sub>A</sub> tightening torques with no indication of tolerance ± 20 %

### 8. Supporting the axis-motor combination



To avoid damage:

- Support the combination so it is free from tension.

### 9. Permissible axes and motors

#### → Note

Malfunction and material damage due to overloading.

The output variables of the motor must not exceed the permissible values of the components used.

Permissible values → [www.festo.com/catalogue](http://www.festo.com/catalogue)

- Limit the motor's output variables accordingly.

- Derive the shaft and motor from the interface codes.

Example: EAMM-A-E20-40A

– Axis interface **E20**

– Motor interface **40A**

Axis interface	Axis <sup>5)</sup>
E20	DMES-18, DGE-18-SP
E32	DMES-25, DGE-25-SP
E48	DMES-40 <sup>2)</sup> , DGE-40-SP <sup>3)</sup>
E72	DMES-63, DGE-63-SP

Motor interface	Motor <sup>6)</sup>
400	EMMS-AS-40
42A	EMMS-ST-42
55A	EMMS-AS-55
57A	EMMS-ST-57
67A	EMCA-EC-67
70A	EMMS-AS-70
87A	EMMS-ST-87
100A	EMME-AS-100, EMMS-AS-100

<sup>5)</sup> Spindle axis DGE-...-SP, positioning axis DMES

<sup>6)</sup> Servo motor EMME-AS/EMMS-AS, stepper motor EMMS-ST, integrated drive EMCA-EC