




Festo AG & Co. KG

Postfach  
73726 Esslingen  
Deutschland  
+49 711 347-0  
[www.festo.com](http://www.festo.com)


## Justierbausatz EADC-E12

### 1. Teileliste



- |     |                              |      |
|-----|------------------------------|------|
| [1] | Nutenstein                   | (2x) |
| [2] | Justierplatte                | (1x) |
| [3] | Schraube M6x30               | (2x) |
| [4] | Vierkantmutter               | (2x) |
| [5] | Justierbolzen                | (2x) |
| [6] | Scheibe                      | (2x) |
| [7] | Schraube M8x40 <sup>1)</sup> | (2x) |

Nicht im Lieferumfang:  
[8] Flächenportal  
EXCH (1x)



### 2. Bestimmungsgemäße Verwendung

Justierbausatz EADC-E12:

Befestigung und Ausrichtung des Flächenportals EXCH. Ausgleich eines Höhenunterschiedes von bis zu 5 mm.

### 3. Sicherheitshinweise und Hinweise zur Montage

#### Vorsicht

Unerwartete Bewegung von Bauteilen.

Verletzung durch Schlag, Stoß, Quetschung.

- Stromversorgung vor Montagearbeiten abschalten.
- Sicherheitshinweise beachten (**→ mitgelieferte Dokumente**).

#### Hinweis

Funktionsstörung und Sachschaden durch unsachgemäße Montage.

Falls die Montagefläche nicht aus Stahl ist:

- Andere Schraube [7] passend zur Einbausituation wählen.
- Gewindetiefe  $\geq 14$  mm auf Montagefläche für die Schrauben [7] vorsehen.
- Sachgemäß montieren (**→ Abschnitt 4**).
- Anziehdrehmomente einhalten.

#### Info









##### Mitgelieferte Dokumente

**→ Beschreibung Flächenportal: EXCH (Mechanischer Einbau)**

- Mindestanzahl und Abstände der Justierbausätze beachten.
- Flächenportal ausrichten.

Zubehör **→ [www.festo.com/catalogue](http://www.festo.com/catalogue)**: EXCH

### 4. Montage



- Nutenstein [1] in der Profilnut (A) platzieren.
- Justierplatte [2] mit den Schrauben [3] an den Nutensteinen [1] leicht fixieren.
- Justierplatte [2] positionieren. Mindestanzahl und Abstände der Justierbausätze beachten (**→ Info**).
- Schrauben [3] festdrehen.

- Die Justierbolzen [5] in die Vierkantmuttern [4] bündig eindrehen.

- Vierkantmuttern [4] inklusive Justierbolzen [5] in die Nut (B) schieben.

- Scheiben [6] unter die Schrauben [7] legen.
- Schrauben [7] mittig im Langloch platzieren.

EADC-E12-	40	60
X [mm]	78	98

- Justierplatte [2] mit den Schrauben [7] auf der Montagefläche leicht fixieren.
- Gabelschlüssel (C) mit  $t < 5$  mm verwenden.  
Bei  $t > 5$  mm fällt der mögliche Höhenausgleich um die Differenz ( $t - 5$ ) geringer aus.

- Flächenportal ausrichten (**→ Info**). Die Justierbolzen [5] hinein- oder herausdrehen ( $h = 6 \dots 11$  mm).
- Ausreichende Einschraubtiefe der Schrauben [7] beachten (bei Stahl  $\geq 8$  mm).

- Schrauben [7]<sup>1)</sup> festdrehen. An den Justierbolzen [5] gegenhalten:
  - Die Justierbolzen [5] nicht verdrehen.
  - Ausrichtung beibehalten.

Kontrolle: Ausrichtung des Flächenportals [8].

<sup>1)</sup> Schraube [7] und das Anziehdrehmoment ist für eine Montage auf Stahl ausgelegt.


**FESTO**

Festo AG & Co. KG

Postfach  
73726 Esslingen  
Germany  
+49 711 347-0  
[www.festo.com](http://www.festo.com)

## Adjusting kit EADC-E12


### 1. Parts list



1	Slot nut	(2x)
2	Adjusting plate	(1x)
3	M6x30 screw	(2x)
4	Square nut	(2x)
5	Adjusting bolt	(2x)
6	Washer	(2x)
7	Screw M8x40 <sup>1)</sup>	(2x)

Not included in delivery:

- 8 Planar surface gantry (1x)  
EXCH



### 2. Intended use

Adjusting kit EADC-E12:

Attachment and alignment of the planar surface gantry EXCH. Compensation of a difference in height of up to 5 mm.

### 3. Safety instructions and notes on mounting

#### Caution

Unexpected movement of components.

Injury due to electric shock, impact, squeezing.

- Switch off power supply before mounting work.
- Observe safety instructions (→ applicable documents).

#### Note

Malfunction and material damage due to incorrect mounting.

If the mounting surface is not made of steel:

- Select a different screw [7] suitable for the installation situation.
- Thread depth  $\geq 14$  mm intended on the mounting surface for the screws [7].
- Mount properly (→ section 4).
- Observe tightening torques.


#### Information

##### Applicable documents


- Description of the planar surface gantry: EXCH (mechanical installation)
  - Observe minimum number and distances of the adjusting kits.
  - Align planar surface gantry.

Accessories → [www.festo.com/catalogue](http://www.festo.com/catalogue): EXCH


### 4. Mounting




- Place slot nuts [1] in the profile slot (A).
- Clamp the adjusting plate [2] to the slot nuts [1] using the screws [3].
- Position the adjusting plate [2]. Observe minimum number and distances of the adjusting kits (→ Info).
- Tighten screws [3].



- Screw adjusting bolts [5] flush into the square nuts [4].





- Push square nuts [4] including adjusting bolts [5] into the slot (B).




- Place washers [6] underneath the screws [7].
- Place screws [7] in the middle of the oblong hole.

- |           |    |    |
|-----------|----|----|
| EADC-E12- | 40 | 60 |
| X [mm]    | 78 | 98 |
- Lightly clamp the adjusting plate [2] to the mounting surface with the screws [7].
  - Use spanner (C) with  $t < 5$  mm.


With  $t > 5$  mm, the possible height compensator is smaller by the difference ( $t - 5$ ).



- Align planar surface gantry (→ Info). Screw the adjusting bolts [5] in or out ( $h = 6 \dots 11$  mm).
- Observe sufficient screw-in depth of the screws 7 (for steel  $\geq 8$  mm).



- Tighten screws [7]<sup>1)</sup>. Apply counter pressure to the adjusting bolt [5]:
  - Do not twist the adjusting bolt [5].
  - Maintain alignment.



Check: alignment of the planar surface gantry [8].

<sup>1)</sup> Screw [7] and the tightening torque are designed for mounting on steel.