

FESTO

Festo AG & Co. KG

Postfach
73726 Esslingen
Deutschland
+49 711 347-0
www.festo.com

Axialausatz EAMM-A-P...-G

1. Bestimmungsgemäße Verwendung

Axialausatz EAMM-A-P...-G:
Verbindung einer Achse mit einem Getriebe in axialer Anordnung zur ange-triebenen Welle (→ Abschnitt 9).

2. Sicherheitshinweise und Hinweise zur Montage

⚠ Warnung

Unerwartete Bewegung von Bauteilen.

Verletzung durch Schlag, Stoß, Quetschung.

- Stromversorgung vor Montagearbeiten abschalten.
- Sicherheitshinweise beachten (→ Mitgeltende Dokumente).

→ Hinweis

Funktionsstörung und Sachschaden durch unsachgemäße Montage.

- Anziehdrehmomente einhalten (→ Abschnitt 7).
 - Schmierfilm auf den Schrauben belassen.
 - Wellen reinigen. Die Kupplung greift nur auf trockenen und fettfreien Wellenzapfen rutschfrei.
 - Ausrichtung der Kupplungsnahe einhalten (→ Abschnitt 6).
 - Kombination abstützen (→ Abschnitt 8):
 - bei weit auskragenden und schweren Motoranbauten
 - bei starken Vibrationen und Schwing-/Schockbelastungen.
- Nach jedem Lösen oder Verdrehen des Motors:
- Referenzfahrt der Achse starten.

ℹ Info


Mitgeltende Dokumente

- Bedienungsanleitung Motor
- Bedienungsanleitung Getriebe
- Bedienungsanleitung Achse

Der Bausatz enthält die maximal erforderlichen Befestigungselemente.


- Benötigte Befestigungselemente wählen (→ Abschnitt 7).

3. Teileliste




- | | | |
|----|---------------|------|
| 1 | Kupplungsnahe | (2x) |
| 2 | Klemmschraube | (2x) |
| 8 | Motorflansch | (1x) |
| 9 | Schraube | (4x) |
| 11 | Schraube | (4x) |
| 12 | Motorflansch | (1x) |
| 13 | Schraube | (4x) |


4. Vormontage Kupplung




- Kupplung auseinanderziehen.
- Zahnkranz (A) auf eine der beiden Kupplungsnahe **1** platzieren.
- Klemmschrauben **2** aufdrehen.
- Kupplungsnahe **1** mit der passenden Bohrung auf den Wellenzapfen (B) schieben.




- Zur genauen Ausrichtung:
- Abstand (X) einhalten (→ Abschnitt 6).
 - Klemmschraube **2** festdrehen.



- Motorflansch **12** mit den Schrauben **11** am Getriebe befestigen.




- Kupplungsnahe **1** mit der passenden Bohrung auf den Wellenzapfen (C) schieben.




- Zur genauen Ausrichtung:
- Abstand (Y) einhalten (→ Abschnitt 6).
 - Klemmschraube **2** festdrehen.

5. Montage



- Motorflansch **8** mit den Schrauben **9** an der Achse befestigen.




- Das Getriebe und die Achse zusammenschieben. Kontrolle: Richtige Stellung der Kupplungsnahe **1** zu einander.
- Das Getriebe über den Motorflansch **12** am Motorflansch **8** mit den Schrauben **13** befestigen.

6. Ausrichtung der Kupplungsnahe **1**

→ Hinweis

Axialkräfte, die auf die Wellen von Getriebe und Achse einwirken, führen zu erhöhtem Verschleiß.

- Abstände X und Y einhalten.




EAMM-A-	Achse	X $\pm 0,3$ [mm]	Y $\pm 0,3$ [mm]
P6-38A-40G	EGSK-33	13,3	28,3
P8-38A-40G	EGSP-33	17,3	24,3
	EGSK-46	26,8	26,3
P10-38A-40G	EGSP-46	27,5	25,6

7. Schraubengrößen und Anziehdrehmomente M_A ¹⁾

EAMM-A-	2 [Nm]	9 [Nm]	11 [Nm]	13 [Nm]
P6-38A-40G	M4x12	4	M5x12	6
P8-38A-40G				
P10-38A-40G			M4x10	3

8. Abstützung der Achs-Getriebe-Motor-Kombination



Um Schäden zu vermeiden:

- Kombination verspannungs-frei abstützen.

9. Zulässige Achsen und Getriebe

→ Hinweis

Funktionsstörung und Sachschaden durch Überlastung.

Die Ausgangsgrößen des Motors dürfen die zulässigen Werte der verwende-ten Komponenten nicht überschreiten.

Zulässige Werte → www.festo.com/catalogue

- Motor-Ausgangsgrößen entsprechend begrenzen.
- Achse und Getriebe aus den Schnittstellencodes ableiten.

Beispiel: EAMM-A-P6-38A-40G

- Achs-Schnittstelle **P6-38A**
- Getriebe-Schnittstelle **40G**

Achs-Schnittstelle	Achse ²⁾
P6-38A	EGSK-33
P8-38A	EGSK-46, EGSP-33
P10-38A	EGSP-46
Getriebe-Schnittstelle	Getriebe
40G	EMGA-40, EMGC-40

¹⁾ Toleranz für Anziehdrehmomente M_A ohne Toleranzangabe $\pm 20\%$

²⁾ Elektroschlitten EGSK/EGSP

FESTO

Festo AG & Co. KG

Postfach
73726 Esslingen
Germany
+49 711 347-0
www.festo.com

Axial kit EAMM-A-P...-G

1. Intended use

Axial kit EAMM-A-P...-G:

Connecting an axis to a gear unit in axial configuration to the driven shaft
(→ section 9).

2. Safety instructions and notes on mounting

⚠ Warning

Unexpected movement of components.

Injury due to impacts or pinching.

- Switch off power supply before mounting work.
- Observe the safety instructions (→ applicable documents).

→ Note

Incorrect mounting can cause malfunction and material damage.

- Observe tightening torques (→ section 7).
- Leave lubricant film on the screws.
- Clean shafts. The coupling only grips dry and grease-free drive shafts.
- Maintain the alignment of the coupling hub (→ section 6).
- Support the combination (→ section 8):
 - If there are far-protruding and heavy motor attachments
 - In the event of severe vibrations and oscillation/shock loads.

Each time after disconnecting or turning the motor:

- Start homing of the axis.

ℹ Information


Applicable documents

- Motor operating instructions
- Gear unit operating instructions
- Axis operating instructions

The kit contains the maximum mounting attachments that may be required.


- Select required mounting components (→ section 7).

3. Parts list




1	Coupling hub	(2x)
2	Clamping screw	(2x)
8	Motor flange	(1x)
9	Screw	(4x)
11	Screw	(4x)
12	Motor flange	(1x)
13	Screw	(4x)


4. Preassembly of the coupling




- Pull apart the coupling.
- Place the ring gear (A) onto one of the two coupling hubs [1].
- Unscrew clamping screws [2].
- Push the coupling hub [1] with the matching drill hole onto the drive shaft (B).




- For accurate alignment:
- Maintain distance (X) (→ section 6).
 - Tighten clamping screw [2].



- Fasten the motor flange [12] to the gear unit with the screws [11].




- Push the coupling hub [1] with the matching drill hole onto the drive shaft (C).




- For accurate alignment:
- Maintain distance (Y) (→ section 6).
 - Tighten clamping screw [2].

5. Mounting



- Fasten the motor flange [8] to the axis with the screws [9].




- Push the gear unit and the axis together.
- Check: Correct position of the coupling hubs [1] in relation to each other.
- Fasten the gear unit over the motor flange [12] to the motor flange [8] with the screws [13].

6. Alignment of the coupling hubs [1]

→ Note

Axial forces on the shafts of the gear unit and axis can result in increased wear.

- Maintain the distances X and Y.




EAMM-A-	Axis	X ± 0.3 [mm]	Y ± 0.3 [mm]
P6-38A-40G	EGSK-33	13.3	28.3
P8-38A-40G	EGSP-33	17.3	24.3
	EGSK-46	26.8	26.3
P10-38A-40G	EGSP-46	27.5	25.6

7. Screw sizes and tightening torques M_{A1}¹⁾

EAMM-A-	[2] [Nm]	[9] [Nm]	[11] [Nm]	[13] [Nm]
P6-38A-40G	M4x12 4	M5x12 6	M4x10 3	M4x12 3
P8-38A-40G				
P10-38A-40G				

8. Support of the axis/gear unit/motor combination



To avoid damage:

- Support the combination so it is free from tension.

¹⁾ Tolerance for tightening torques M_A without indication of tolerance $\pm 20\%$

9. Permissible axes and gear units

→ Note

Malfunction and material damage due to overloading.

The output variables of the motor must not exceed the permissible values of the components used.

Permissible values → www.festo.com/catalogue

- Limit motor output variables accordingly.

- Derive the axis and gear unit from the interface codes.

Example: EAMM-A-P6-38A-40G

- Axis interface P6-38A

- Gear unit interface 40G

Axis interface	Axis ²⁾
P6-38A	EGSK-33
P8-38A	EGSK-46, EGSP-33
P10-38A	EGSP-46
Gear unit interface	Gear units
40G	EMGA-40, EMGC-40

²⁾ Electric slide EGSK/EGSP