

FESTO

Festo AG & Co. KG

Postfach
73726 Esslingen
Deutschland
+49 711 347-0
www.festo.com

Axialausatz EAMM-A-R...-G/H

1. Bestimmungsgemäße Verwendung

Axialausatz EAMM-A-R...-G/H

Verbindung einer Achse mit einem Getriebe in axialer Anordnung zur angetriebenen Welle (→ Abschnitt 10).

2. Sicherheitshinweise und Hinweise zur Montage

⚠ Warnung

Unerwartete Bewegung von Bauteilen.

Verletzung durch Schlag, Stoß, Quetschung.

- Stromversorgung vor Montagearbeiten abschalten.
- Sicherheitshinweise beachten (→ Mitgeltende Dokumente).

→ Hinweis

Funktionsstörung und Sachschaden durch unsachgemäße Montage.

- Anziehdrehmomente einhalten (→ Abschnitt 9).
 - Schmierfilm auf den Schrauben belassen.
 - Wellen/Hohlwelle reinigen. Die Kupplung greift nur auf trockenen und fettfreien Wellenoberflächen rutschfrei.
 - Kupplungsnaben **1** reinigen:
 - Spannzapfen (G) am Außendurchmesser entfetten. Spreizdornkonus (H) gefettet lassen.
 - Klemmbohrung entfetten.
 - Ausrichtung der Kupplungsnabe **1** einhalten (→ Abschnitt 8).
 - Kombination abstützen (→ Abschnitt 7):
 - bei weit auskragenden und schweren Motoranbauten
 - bei starken Vibrationen und Schwing-/Schockbelastungen.
- Nach jedem Lösen oder Verdrehen des Motors:
- Referenzfahrt der Achse starten.

ℹ Info



Mitgeltende Dokumente

- Bedienungsanleitung Motor
- Bedienungsanleitung Getriebe
- Bedienungsanleitung Achse

Der Bausatz enthält die maximal erforderlichen Befestigungselemente.


- Benötigte Befestigungselemente wählen (→ Abschnitt 9).

Bei der Zahnriemenachse ELGG/ELGR sind diese Axialausätze für die Montage auf allen vier Achsseiten vorgesehen (→ folgendes Bild).




- | | | |
|----|------------------|------|
| 1 | Kupplungsnabe | (2x) |
| 2 | Klemmschraube | (1x) |
| 3 | Klemmschraube | (1x) |
| 4 | Kupplungsgehäuse | (1x) |
| 5 | Nutenstein | (2x) |
| 6 | Schraube | (4x) |
| 8 | Motorflansch | (1x) |
| 9 | Schraube | (4x) |
| 11 | Schraube | (4x) |
| 12 | Motorflansch | (1x) |
| 13 | Schraube | (4x) |

4. Montagevorbereitung



- Schraubendreher in die Aussparung der Abdeckung im Antriebsdeckel (B) stecken. Abdeckung abheben.

5. Vormontage Kupplung








- Kupplung auseinanderziehen.
- Zahnkranz (C) auf eine der beiden Kupplungsnaben **1** platzieren.
- Klemmschraube **2** / **3** aufdrehen.
- Kupplungsnabe **1** mit dem Spannzapfen (G) bis zum Anschlag in die Hohlwelle (E) schieben.
- Klemmschraube **3** festdrehen.

ℹ Info


Zur Kupplungsnabe **1** mit Spannzapfen (G):
Wenn der Spreizdornkonus (H) fest sitzt, kann nicht montiert werden. Zur Demontage existiert ein Abdrückgewinde M_1 (→ Abschnitt 9).
• Festsitzenden Spreizdornkonus (G) durch Eindrehen einer Schraube mit Gewinde M_1 herausdrücken.

- Motorflansch **12** mit den Schrauben **11** am Getriebe befestigen.




- Kupplungsnabe **1** mit der passenden Bohrung auf den Wellenzapfen (F) schieben.


6. Montage EAMM-A-R...-G/H




- Nutensteine **5** bündig in die Nuten des Antriebsdeckels (B) schieben.



- Das Kupplungsgehäuse **4** mit den Schrauben **6** an den Nutensteinen **5** befestigen.




- Motorflansch **8** mit den Schrauben **9** am Kupplungsgehäuse **4** befestigen.



- Das Getriebe und die Achse zusammenschieben.
Kontrolle: Richtige Stellung der Kupplungsnaben **1** zu einander.

- Das Getriebe über den Motorflansch **12** mit den Schrauben **13** am Motorflansche **8** befestigen.




7. Abstützung der Achs-Getriebe-Motor-Kombination

- Um Schäden zu vermeiden:
• Kombination verspannungsfrei abstützen.

8. Ausrichtung der Kupplungsnabe **1**

→ Hinweis

Axialkräfte, die auf die Wellen von Getriebe und Achse einwirken, führen zu erhöhtem Verschleiß.
• Abstand Y einhalten.



EAMM-A-	Y ^{±0,3} [mm]
R38-40G	26,1
R38-60G	35,1
R38-60H	
R48-60G	35,1
R48-60H	

9. Schraubengrößen und Anziehdrehmomente M_A ¹

→ Hinweis

Bei einem zu hohen Anziehdrehmoment, insbesondere das der Schraube **3**, verschlechtern sich die technischen Eigenschaften (Lebensdauer, Verschleiß) der Achse.

- Anziehdrehmoment einhalten.

EAMM-A-	2 [Nm]	3 [Nm]	6 [Nm]			
R38-40G	M3x12	2	M4x12	4	M5x20	6
R38-60G						
R38-60H						
R48-60G	M4x12	4	M5x18	9	M5x25	
R48-60H						

EAMM-A-	9 [Nm]	11 [Nm]	13 [Nm]	M₁			
R38-40G	M5x12	6	M4x10	3	M4x12	3	M5
R38-60G	M5x16		M5x10	6	M4x20		M6
R38-60H							
R48-60G							
R48-60H							

10. Zulässige Achsen und Getriebe

→ Hinweis

Funktionsstörung und Sachschaden durch Überlastung.

Die Ausgangsgrößen des Motors dürfen die zulässigen Werte der verwendeten Komponenten nicht überschreiten.

Zulässige Werte → www.festo.com/catalogue

- Motor-Ausgangsgrößen entsprechend begrenzen.

• Achse und Getriebe aus den Schnittstellencodes ableiten.
Beispiel: EAMM-A-R38-40G

- Achs-Schnitstellen R38
- Getriebe-Schnitstellen 40G

Achs-Schnitstellen	Achse ²⁾
R38	ELGG-45, ELGR-45
R48	ELGG-55, ELGR-55

Getriebe-Schnitstellen	Getriebe
40G	EMGA-40, EMGC-40
60G	EMGA-60...SAS/-SST
60H	EMGA-60...EAS, EMGC-60

¹⁾ Toleranz für Anziehdrehmomente M_A ohne Toleranzangabe ± 20 %

²⁾ Zahnriemenachse ELGG/ELGR

FESTO

Festo AG & Co. KG

Postfach
73726 Esslingen
Germany
+49 711 347-0
www.festo.com

Axial kit EAMM-A-R...-G/H

1. Intended use

Axial kit EAMM-A-R...-G/H

Connecting an axis to a gear unit in axial configuration to the driven shaft (→ section 10).

2. Safety instructions and notes on mounting

⚠ Warning

Unexpected movement of components.

Injury due to impacts or pinching.

- Switch off power supply before mounting work.
- Observe the safety instructions (→ applicable documents).

→ Note

Incorrect mounting can cause malfunction and material damage.

- Observe tightening torques (→ section 9).
- Leave lubricant film on the screws.
- Clean shafts/hollow shafts. The coupling only grips without sliding on a dry and grease-free shaft surface.
- Clean the coupling hubs [1].
- Degrease the clamping pivot (G) at the outside diameter. Do not degrease the expanding mandrel cone (H).
- Degrease clamping hole.
- Maintain the alignment of the coupling hub [1] (→ section 8).
- Support the combination (→ section 7):
 - If there are far-protruding and heavy motor attachments
 - In the event of severe vibrations and oscillation/shock loads.

Each time after disconnecting or turning the motor:

- Start homing of the axis.

ℹ Information


Applicable documents

- Motor operating instructions
- Gear unit operating instructions
- Axis operating instructions

The kit contains the maximum mounting attachments that may be required.

- Select required mounting components (→ section 9).


With the toothed belt axis ELGG/ELGR, these axial kits are intended for engine assembly on all four sides of the axis (→ following figure).



3. Parts list EAMM-A-R...-G/H


[1]	Coupling hub	(2x)
[2]	Clamping screw	(1x)
[3]	Clamping screw	(1x)
[4]	Coupling housing	(1x)
[5]	Slot nut	(2x)
[6]	Screw	(4x)
[8]	Motor flange	(1x)
[9]	Screw	(4x)
[11]	Screw	(4x)
[12]	Motor flange	(1x)
[13]	Screw	(4x)

4. Preparations for mounting







- Insert a screwdriver into the recess in the drive cover (B). Lever off the cover.

5. Preassembly of the coupling



- Pull apart the coupling.
- Place the ring gear (C) onto one of the two coupling hubs [1].
- Unscrew clamping screw [2]/[3].
- Push the coupling hub [1] with the clamping pivot (G) into the hollow shaft (E) up to the stop.
- Tighten clamping screw [3].




ℹ Information

On the coupling hub [1] with clamping pivot (G):

If the expanding mandrel cone (H) is stuck, the unit cannot be mounted. For dismantling, there is a forcing spindle M₁ (→ section 9).


- Push out the stuck expanding mandrel cone (G) by turning in a screw with M₁ thread.

- Fasten the motor flange [12] to the gear unit with the screws [11].




- Push the coupling hub [1] with the matching drill hole onto the drive shaft (F).


6. Mounting EAMM-A-R...-G/H




- Insert slot nuts [5] flush into the slots of the drive cover (B).



- Fasten the coupling housing [4] to the slot nuts [5] with the screws [6].




- Fasten the motor flange [8] to the coupling housing [4] with the screws [9].



- Push the gear unit and the axis together.

Check: Correct position of the coupling hubs [1] in relation to each other.

- Fasten the gear unit over the motor flange [12] to the motor flange [8] with the screws [13].



To avoid damage:


- Support the combination so it is free from tension.

8. Alignment of the coupling hub [1]

→ Note

Axial forces on the shafts of the gear unit and axis can result in increased wear.

- Observe distance Y.



EAMM-A-

	Y ±0.3 [mm]		
R38-40G	26.1		
R38-60G	35.1		
R38-60H			
R48-60G	35.1		
R48-60H			

9. Screw sizes and tightening torques M_A¹

→ Note

If the tightening torque is too high, in particular of screw [3], the technical characteristics of the axis will be impaired (service life, wear).

- Observe the tightening torque.

EAMM-A-	[2]	[3]	[6]
R38-40G	M3x12	2	M5x20
R38-60G			
R38-60H			
R48-60G	M4x12	4	M5x25
R48-60H			

EAMM-A-	[9]	[11]	[13]	M ₁
R38-40G	M5x12	6	M4x10	M5
R38-60G	M5x16		M5x10	M6
R38-60H				
R48-60G				
R48-60H				

10. Permissible axes and gear units

→ Note

Malfunction and material damage due to overloading.

The output variables of the motor must not exceed the permissible values of the components used.

Permissible values → www.festo.com/catalogue

- Limit motor output variables accordingly.

• Derive the axis and gear unit from the interface codes.

Example: EAMM-A-R38-40G

- Axis interface **R38**
- Gear unit interface **40G**

Axis interface	Axis ²⁾
R38	ELGG-45, ELGR-45
R48	ELGG-55, ELGR-55

Gear unit interface	Gear units
40G	EMGA-40, EMGC-40
60G	EMGA-60...-SAS/-SST
60H	EMGA-60...-EAS, EMGC-60

¹⁾ Tolerance for tightening torques M_A without indication of tolerance ± 20 %²⁾ Toothed belt axis ELGG/ELGR