




Drucksensor VMPA-FB-PS...

Festo AG & Co. KG

Postfach
D-73726 Esslingen
++49/(0)711/347-0
www.festo.com

1. Teileliste



- [1] Drucksensor
VMPA-FB-PS...
- [2] Schraube M3x9 (selbst
schneidend)

Nicht im Lieferumfang:

- [3] Dichtung
VMPA1-DP...
- [4] MPA-S Pneumatik
- [5] CPX-Terminal

Bestimmungsgemäß dient der
Drucksensor [1] zur Drucküber-
wachung in der Ventilinsel
MPA-S.

⚠ Warnung

Elektrischer Schlag und unkontrollierte Bewegungen!

Verletzungen können die Folge sein.

- Stellen Sie sicher, dass im strom- und drucklosen Zustand montiert wird.

→ Hinweis


Beschädigung von Bauelementen und Funktionsstörungen!

- Achten Sie darauf, dass Sie die Kontaktflächen an den seitlichen Steck-
verbindungen des Drucksensors [1] nicht berühren. Dies sind elektro-
statisch gefährdete Bauelemente.


Info

- Beachten Sie auch:
 - die MPA-S Pneumatik-Beschreibung P.BE-MPA-...
 - die CPX-EA-Modul-Beschreibung P.BE-CPX-EA-...
 - die unterschiedlichen Funktionen der Dichtungsvarianten (→ MPA-S
Pneumatik-Beschreibung P.BE-MPA-... im Kapitel Komponenten-
beschreibung).

2. Anschluss, mechanisch




- Drehen Sie die vormon-
tierten Schrauben [2] aus
dem Drucksensor [1].




- Trennen Sie die strom- und
drucklose MPA-S Pneu-
matik [4] an der ge-
wünschten Position.
- Prüfen Sie die existierende
Dichtung [3] auf Beschä-
digung. Tauschen Sie die
Dichtung ggf. aus.


Folgende Dichtungsvarianten
sind zulässig (→ Info):



- Montieren Sie den Druck-
sensor [1] (→ Bild).
- Setzen Sie die Dichtungen [3]
dabei auf die dafür vorge-
sehenen Führungsstifte.
- Prüfen Sie die korrekte Lage
der Dichtungen und der
Komponenten zueinander.



- Drehen Sie die Schrauben [2]
in der Reihenfolge A, B, C
erst leicht an und an-
schließend fest. Halten Sie
das zulässige Anziehdreh-
moment ein.




Pressure sensor VMPA-FB-PS...

FESTO

Festo AG & Co. KG

Postfach
D-73726 Esslingen
++49/(0)711/347-0
www.festo.com

1. Parts list



- ① Pressure sensor VMPA-FB-PS...
 - ② Screw M3x9 (self-tapping)
Not included in scope of delivery:
 - ③ Seal VMPA1-DP...
 - ④ MPA-S pneumatics
 - ⑤ CPX terminal
- The pressure sensor ① has been designed for monitoring the pressure in the MPA-S valve terminal.

⚠ Warning

Electric shock and uncontrolled movements!

This may result in injury.

- Make sure that assembly is carried out when the device is disconnected from the power and compressed air supplies.

→ Note


Damage to components and functioning faults!

- Make sure that you do not touch the contact surfaces on the side of the pressure sensor ①. These are electrostatically sensitive components.


i Information

- Note also:
 - the MPA-S Pneumatics Manual P.BE-MPA-...
 - the CPX-EA-Module Manual P.BE-CPX-EA-...
 - the different functions of the sealing variants (→ MPA-S Pneumatics Manual P.BE-MPA-... in the chapter "Description of components").


2. Connection, mechanical





- Remove the pre-fitted ② screws from the pressure sensor ①.




- Separate the current less and pressure less MPA-S pneumatics ⑤ on the desired position.
- Check the seal ③ for damage. If necessary, replace the seal.



The following seal variants are permitted (→Information):



- Mount the pressure sensor ① (→Fig.).
- Place seals ③ on the guide pins intended for this purpose.
- Check that the position of the seals and of the components in relation to each other is correct.



- Screw in slightly the screws ② in the sequence A, B, C and then tighten. Maintain the permitted tightening torque.