


FESTO

Festo AG & Co. KG

Postfach
D-73726 Esslingen
+49/(0)711/347-0
www.festo.com


Installationsbausatz HMIXF-RP/FP-2



- 1. Installationsbausatz**
B
A
[1] Installationsbausatz
HMIXF-RP/FP-2
(A) Zylinderschraube (2x)
M6x20
(B) Senkschraube (2x)
M6x16

Bestimmungsgemäß dient der Installationsbausatz [1] als Übergabestelle von Energieleitungen aus der Energieführungskette (E-Kette) [3] in die Energieführungskette (E-Kette) [2] beim Aufbau von Raum- und Flächenportalsystemen.

2. Montagebeispiel



- [1] Installationsbausatz
HMIXF-RP/FP-2
[2] E-Kette
X-Achse
[3] E-Kette
Y-Achse
[4] Auflageprofil
HMIA-E...X

⚠ Warnung

Verletzungsgefahr durch elektrische Spannung!

Nach der Montage:

- Verbinden Sie den Bausatz [1] mit dem Schutzleitersystem
→ Montageanleitung Erdungsbau (beiliegend in HMVS-DL25/DL40)

→ Hinweis


- Beachten Sie, dass nur Befestigungskombinationen aus der Tabelle zulässig sind.
- Verwenden Sie nur zulässige E-Ketten laut Katalog
→ www.festo.com/catalogue.
- Halten Sie die zulässigen Anziehdrehmomente ein (→ Tabelle).

i Info

- Beachten Sie die Montagereihenfolge
→ Montageübersicht (beiliegend in HMVS-DL25/DL40)
- Wählen Sie die Befestigungselemente (Schrauben, usw.) für Ihre Kombination (→ Tabelle).
- Beachten Sie die Bildzuordnung für Ihre Kombination (→ Tabelle).
- Verfahren Sie die Achsen von Hand (Y-Modul mit vollem Hub in X-Richtung) und überprüfen Sie dabei die Installation bzw. das leichte Abrollen der E-Ketten.


3. Montage Installationsbausatz [1]

Bild 1




- [1] Installationsbausatz
HMIXF-RP/FP-2
[5] Versteifungsbausatz
HMVV-RP/FP

Bild 2




- [1] Installationsbausatz
HMIXF-RP/FP-2
[2] E-Kette
X-Achse

Bild 3




- [1] Installationsbausatz
HMIXF-RP/FP-2
[2] E-Kette
X-Achse

Bild 4




- [1] Installationsbausatz
HMIXF-RP/FP-2
[2] E-Kette
X-Achse

4. Montage der E-Kette [2]





- [5] Versteifungsbausatz
HMVV-RP/FP
[6] Installationsbausatz
HMIXB-RP/FP...
[7] Adapterbausatz
HMVW-DL... / HMVS-RF...
[8] Grundbausatz
HMV...-RP/FP...




- Lesen Sie dazu die Montageanleitungen für das Auflageprofil [4] und die Bausätze [5] bis [8].


- Befestigen Sie die E-Kette [2] bündig im Auflageprofil [4].




- Befestigen Sie das Auflageprofil [4] zunächst nur lose auf den Installationsbausätzen [6].



- Befestigen Sie den Installationsbausatz [1] zunächst nur lose am Versteifungsbausatz [5] mit den Schrauben (A) (→ Bild 1).



- Richten Sie die E-Kette [2] je nach Antriebseinheit wie folgt aus:
 - auf dem Installationsbausatz [1] (→ Bild 2 bis Bild 4)
 - mit dem Auflageprofil [4] auf den Installationsbausätzen [6].
- Befestigen Sie das Auflageprofil [4] auf den Installationsbausätzen [6].



[1] Bausatz HMIXF-RP/FP-2

Anbaukomponente	[5] HMVV-RP/FP	[2] E-Kette
Antriebseinheit X-Achse		DGE-63-...- ZR-KF- Linearantrieb
Antriebseinheit Y-Achse		alle elektr. pneum.
→ Bild	1	2 3 4
	[M _A ¹⁾ [Nm]]	

A Zylinderschraube nach DIN 912

M6x20	10	2x	
-------	----	----	--

B Senkschraube nach DIN 7991

M6x16	6	2x	2x
-------	---	----	----

- Justieren Sie die E-Kette [2] so, dass der zulässige Biegeradius der E-Kette nicht unterschritten wird.

Nach der Justage der E-Kette [2]:

- Drehen Sie die Schrauben (A) am Versteifungsbausatz [5] fest.


FESTO

Festo AG & Co. KG

Postfach
D-73726 Esslingen
++49/(0)711/347-0
www.festo.com

Installation kit HMIXF-RP/FP-2


1. Installation kit



- [1] Installation kit HMIXF-RP/FP-2
- (A) Socket head screw (2x)
M6x20
- (B) Countersunk screw (2x)
M6x16

The installation kit [1] is intended as a transfer point for power supply lines from the energy chain (E-chain) [3] into the energy chain (E-chain) [2] when mounting 3D and planar surface gantry systems.

2. Assembly example



- [1] Installation kit HMIXF-RP/FP-2
- [2] E-chain X-axis
- [3] E-chain Y-axis
- [4] Support profile HMIA-E...-X

Warning

Risk of injury due to voltage!

After assembly:

- Connect the kit [1] to the protective circuit
→ assembly instructions for earthing kit (included with HMVS-DL25/40)

Note


- Note that only the assembly combinations shown in the table are permissible.
- Use only permitted E-chains as specified in the catalogue
→ www.festo.com/catalogue.
- Observe the permitted tightening torques (→ Table).

Information

- Follow the mounting sequence
→ Assembly overview (included with HMVS-DL25/DL40)
- Select the mounting components (screws etc.) for your combination (→ Table).
- Observe the reference figures/illustrations for your combination (→ Table).
- Move the axes by hand (Y-module with full stroke in the X-direction) while checking the installation or verifying that the E-chains roll off easily.


3. Mounting the installation kit [1]

Fig. 1




- [1] Installation kit HMIXF-RP/FP-2
- [5] Reinforcing kit HMVV-RP/FP

Fig. 2




- [1] Installation kit HMIXF-RP/FP-2
- [2] E-chain X-axis

Fig. 3




- [1] Installation kit HMIXF-RP/FP-2
- [2] E-chain X-axis

Fig. 4



- [1] Installation kit HMIXF-RP/FP-2
- [2] E-chain X-axis


4. Mounting the E-chain [2]




- [5] Reinforcing kit HMVV-RP/FP
- [6] Installation kit HMIXB-RP/FP...
- [7] Adapter kit HMVW-DL... / HMVS-RF...
- [8] Basic kit HMV...-RP/FP...

- Refer to the assembly instructions for the support profile [4] and the kits [5] to [8] for this purpose.


- Fasten the E-chain [2] flush with the support profile [4].




- Fasten the support profile [4] at first only loosely onto the installation kits.




- With the screws (A), fasten the installation kit [1] at first only loosely onto the reinforcing kit [5] (→ Fig. 1).




- Adjust the E-chain [2] as follows, depending on the drive unit:
 - on the installation kit [1] (→ Fig. 2 to Fig. 4)
 - with the support profile [4] on the installation kits [6].
- Fasten the support profile [4] onto the installation kits [6].



- Adjust the E-chain [2] so that the maximum permitted bending radius of the E-chain [2] is not exceeded.



- After adjusting the E-chain [2]:
 - Tighten the screws (A) on the reinforcing kit [5].



[1] Kit	HMIXF-RP/FP-2			
Attachment component	[5] HMVV-RP/FP	[2] E-chain		
Drive unit X-axis		DGE-63-...- ZR-KF-	DGE-63-...- ZR-RF-	
Drive unit Y-axis		Linear drive		
→ Fig.	1	2	3	4
	$M_A^{1)} [Nm]$			
A Socket head screw to DIN 912	M6x20	10	2x	
B Countersunk screw to DIN 7991	M6x16	6	2x	2x